Oil Field Environmental Incident Summary

Responsible Party: Marathon Oil company

Well Operator: MARATHON OIL COMPANY

Well Name: JONES USA 14-14H

Field Name: REUNION BAY Well File #: 19514

Date Incident: 12/31/2013 Time Incident: 13:30 Facility ID Number:

County: MCKENZIE Twp: 151 Rng: 94 Sec: 14 Qtr: SW SW

Location Description: Stuffing box leak; contained to pad surface

Submitted By: Brenda Rettinger Received By:

Contact Person: Brenda Rettinger

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:2 MilesDistance Nearest Water Well:1 Miles

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2.9	barrels	2.9	barrels	2.9	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

None

Inspected: Written Report Received: 2/6/2014 Clean Up Concluded: 12/31/2013

Risk Evaluation:

None

Areal Extent:

None

Potential Environmental Impacts:

None, fluid was recovered from frozen soil

Action Taken or Planned:

Vac truck called immediately to remove oil from frozen ground. Light covering of oil on snow also picked up. Fluid was cleaned up quickly enough to avoid infiltration through frozen ground. Voicemail left for Allen Christensen (NDIC) and Jeff Desjarlais (BIA); phone notification to Harley Pace with MHA Energy. Online spill report was attempted 12/31/13, but a 500- Server Error prevented submission.

Wastes Disposal Location: Recovered oil will be recycled.

Agencies Involved: BIA, MHA Energy

Updates

Date: 1/3/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forwarded to BIA/Tribal Authorities.